




CONDITION REPORT

2020 Mini Cooper 5-puertas (F55) Cooper 5-puertas (F55)
100HP

2020 | 73753 KM | Manuelle | Essence | 100 kw

Seller Disclosure



3796LJN

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Starlight Blue
HP	100 kw
VIN	WMWXU710302M22209
Technical Inspection	
DUA	No
Mise en circulation	28/08/2020
Last Service Date	-

- 2^e CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus

Equipement

Notes publique

Inspection


DOCUMENTACION EN CUSTODIA DE
GESTORIA
EQUIPAMIENTO:
;
ACC.CONF ; CC ; LED ; NAV* ; PDC* ;
Pepper

Emplacement	-
Auction Centre	Madrid

Inspection

Emplacement	-
Auction Centre	Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -