



CONDITION REPORT

2021 DS DS 7 CROSSBACK 1.6 E-Tense 225 PERFORMANCE
LINE Auto 225HP





2021 | 45291 KM | auto | hybrid | 225 hp

Seller Disclosure



0723LVL

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Cristal
HP	225 hp
VIN	VR1J4DGZUMY540559
Technical Inspection	
DUA	No
Mise en circulation	20/12/2021
Last Service Date	-

-  2^e CHAVE
-  CARNET D'ENTRETIEN
-  VAT
-  Vendus



Equipement

Notes publique

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Inspection

Emplacement	Madrid
Auction Centre	Madrid

Inspection

Emplacement	Madrid
Auction Centre	Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-