



CONDITION REPORT

2018 Renault KANGOO EXPRESS Profesional dCi 55kW
(75CV) Euro 6 75HP





2018 | 132157 KM | Manuelle | Diesel | 75 hp

Seller Disclosure



6866KPG

| | |
|-----------------------------|-------------------|
| Engine Size | - |
| Places assises | - |
| Nombre de portes | - |
| Type de carrosserie | - |
| Couleur carrosserie | Blanco |
| HP | 75 hp |
| VIN | VF1FW50S161152007 |
| Technical Inspection | |
| DUA | No |
| Mise en circulation | 09/12/2018 |
| Last Service Date | - |

-  2ª CHAVE
-  CARNET D'ENTRETIEN
-  VAT
-  Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

| | |
|-----------------------|--------|
| Emplacement | Madrid |
| Auction Centre | Madrid |

Inspection

| | |
|-----------------------|--------|
| Emplacement | Madrid |
| Auction Centre | Madrid |

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-