



CONDITION REPORT

2019 Volkswagen CADDY Profesional Furgon 1.4 TGI 81kW
BM 110HP

2019 | 1 KM | Manuelle | lpg | 110 hp

Seller Disclosure



9015KZV

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco candy sÃ³lido
HP	110 hp
VIN	WV1ZZZ2KZKX135612
Technical Inspection	
DUA	No
Mise en circulation	29/08/2019
Last Service Date	-



2º CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement	Madrid
Auction Centre	Madrid


Inspection

Emplacement	Madrid
Auction Centre	Madrid


Damage Assesment




Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-