



CONDITION REPORT

2019 BMW X7 xDrive40i 340HP

2019 | 1 KM | auto | Essence | 340 hp

Seller Disclosure



7710KWZ

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Carbonschwarz
HP	340 hp
VIN	WBACW21060LS05209
Technical Inspection	
DUA	No
Mise en circulation	16/05/2019
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement Madrid
Auction Centre Madrid

Inspection

Emplacement Madrid
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-