



CONDITION REPORT

2020 DS DS 7 CROSSBACK BlueHDi DE 96kW (130CV)
PERFORMANCE LINE todoterre HP

2020 | 77831 KM | Manuelle | Diesel |

Seller Disclosure



2848LDX

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco Banquise - P0WP
HP	-
VIN	VR1JCYHZJKY225213
Technical Inspection	
DUA	No
Mise en circulation	17/01/2020
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Emplacement	-
Auction Centre	Madrid

Inspection

Emplacement	-
Auction Centre	Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-