



# CONDITION REPORT

2021 Peugeot 3008 Peugeot 3008 1.5 BlueHDi 96kW (130CV)  
S&S Allure P HP

2021 | 110236 KM | Manuelle | Diesel |

Seller Disclosure



**9955LNF**

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco Nacarado (3 capas)
HP	-
VIN	VF3MCYHZMMS080352
Technical Inspection	
DUA	No
Mise en circulation	22/03/2021
Last Service Date	-

2ª CHAVE

CARNET D'ENTRETIEN

VAT

Vendus



## Equipement

## Notes publique

## Inspection

IMPORTANTE: VER PERITACIÓN  
(Informe Tecnico) PARA MÁS FOTOS +  
COMPROBAR POSIBLES DAÑOS +  
INFORMACIÓN ADICIONAL

**Emplacement** -  
**Auction Centre** Madrid

## Inspection

**Emplacement** -  
**Auction Centre** Madrid

## Damage Assesment



Détail du dommage :-  
Type de dommage :-  
Taille du dommage :-