



CONDITION REPORT

2020 BMW X1 X1 sDrive18dA Business 150HP

2020 | 100857 KM | Manuelle | Diesel | 150 hp

Seller Disclosure



3761LFS

Engine Size	1995 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	PINTURA NORMAL
HP	150 hp
VIN	WBA71AC0005R14780
Technical Inspection	
DUA	No
Mise en circulation	24/02/2020
Last Service Date	-

- 2ª CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

Inspection

<https://www.manheimtransportatucoche.es/es/transportas/manheim>

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-

Type de dommage :-

Taille du dommage :-