



CONDITION REPORT

2020 Mini Cooper Cabrio (F57) Cooper Cabrio (F57) 100HP

2020 | 37317 KM | auto | Essence | 100 kw

Seller Disclosure



8421LLS

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Moonwalk Grey
HP	100 kw
VIN	WMWWJ310203L98413

Technical Inspection

DUA	No
Mise en circulation	21/12/2020
Last Service Date	-

-  2^e CHAVE
-  CARNET D'ENTRETIEN
-  VAT
-  Vendus



Equipement

Notes publique

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
<a
href="http://soportemanheim.es/E/8421LLS.htm"
target="_blank">CLICK AQUÍ PARA VER
EL EQUIPAMIENTO
COMPLETO


Emplacement
Auction Centre

Madrid-ES34
Madrid


Inspection

Emplacement Madrid-ES34
Auction Centre Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -



Détail du dommage : -
Type de dommage : -
Taille du dommage : -