



CONDITION REPORT

2019 Peugeot PARTNER Furgon Confort L1 1.6 BlueHDI
55KW (75) 75HP

2019 | 1 KM | Manuelle | Diesel | 75 hp

Seller Disclosure



7334KWN

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco
HP	75 hp
VIN	VF37ABHW6JJ761842
Technical Inspection	
DUA	No
Mise en circulation	29/04/2019
Last Service Date	-

- 2ª CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement	Madrid
Auction Centre	Madrid

Inspection

Emplacement	Madrid
Auction Centre	Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-