



# CONDITION REPORT

2018 Peugeot PARTNER Furg.Confort PackL1 BlueHDi 73KW (100) 100HP

2018 | 1 KM | Manuelle | Diesel | 100 hp

Seller Disclosure



**3567KSH**

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco
HP	100 hp
VIN	VF37ABHY6JN524800
<b>Technical Inspection</b>	
DUA	No
Mise en circulation	18/12/2018
Last Service Date	-

- 2º CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



## Equipement

## Notes publique

## Inspection


IMPORTANTE: VER PERITACIÓN  
(Informe Tecnico) PARA COMPROBAR  
POSIBLES DAÑOS E INFORMACIÓN  
ADICIONAL

<b>Emplacement</b>	Madrid
<b>Auction Centre</b>	Madrid

## Inspection

<b>Emplacement</b>	Madrid
<b>Auction Centre</b>	Madrid

## Damage Assesment



Détail du dommage :-

Type de dommage :-

Taille du dommage :-