



CONDITION REPORT

2021 BMW X2 X2 2.0 SDRIVE20D AUTO 190HP

2021 | 115434 KM | auto | Diesel | 190 hp

Seller Disclosure



5021LMN

Engine Size	1995 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	A96MINERALWEISS META
HP	190 hp
VIN	WBAYK910205S94792
Technical Inspection	
DUA	No
Mise en circulation	10/02/2021
Last Service Date	-

- ☒ 2ª CHAVE
- ☒ CARNET D'ENTRETIEN
- ☒ VAT
- ☒ Vendus



Equipement

Notes publique


Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim>

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid



Détail du dommage : -

Type de dommage : -

Taille du dommage : -