



CONDITION REPORT

2021 Mazda CX-5 CX-5 (O)2.2 D 110KW ZENITH SAFETY 2WD
150HP

2021 | 116517 KM | Manuelle | Diesel | 150 hp

Seller Disclosure

0092LNB

Engine Size	2191 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	METALIZADA
HP	150 hp
VIN	JMZKF6W1690121697
Technical Inspection	
DUA	No
Mise en circulation	10/03/2021
Last Service Date	-

- ✗ 2º CHAVE
- ✗ CARNET D'ENTRETIEN
- ✓ VAT
- ✗ Vendus



Equipement

Notes publique


Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Emplacement
Auction Centre - Madrid

Inspection

Emplacement
Auction Centre - Madrid



Détail du dommage : -

Type de dommage : -

Taille du dommage : -