



CONDITION REPORT

2019 BMW X1 X1 SDRIVE18D 150HP

2019 | 108851 KM | Manuelle | Diesel | 150 hp


Seller Disclosure



7769KVC

Engine Size	1995 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	yellow
HP	150 hp
VIN	WBAJH51050EK94231
Technical Inspection	
DUA	No
Mise en circulation	05/03/2019
Last Service Date	-

- ✗ 2^e CHAVE
- ✗ CARNET D'ENTRETIEN
- ✓ VAT
- ✗ Vendus



Equipement

Notes publique

Inspection

CALCULA TU TRANSPORTE

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid



Détail du dommage : -

Type de dommage : -

Taille du dommage : -