



CONDITION REPORT

2022 BMW 118d (F40) 118d (F40) 110HP

2022 | 92409 KM | auto | Diesel | 110 kw

Seller Disclosure



9215LWL

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Skyscraper Grau metalizado
HP	110 kw
VIN	WBA7M910607K59151
Technical Inspection	
DUA	No
Mise en circulation	22/02/2022
Last Service Date	-



2^a CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement	Notes publique	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Emplacement - Auction Centre Madrid

Inspection
Emplacement - Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-