



CONDITION REPORT

2020 HYUNDAI TUCSON TUCSON 1.6 CRDI 100KW 48V
STYLE DT 2WD 136HP

2020 | 92938 KM | Manuelle | | 136 hp

Seller Disclosure



9268LGK

Engine Size	1598 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	POLAR WHITE
HP	136 hp
VIN	TMAJ3817GLJ044804
Technical Inspection	
DUA	No
Mise en circulation	22/05/2020
Last Service Date	-

- ✘ 2^o CHAVE
- ✘ CARNET D'ENTRETIEN
- ✔ VAT
- ✘ Vendus



Equipement

Notes publique


Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> **Emplacement** -
Auction Centre Madrid **CALCULA TU TRANSPORTE**

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-

Type de dommage :-

Taille du dommage :-