



CONDITION REPORT

2020 BMW X4 xDrive20d (G02) X4 xDrive20d (G02) 140HP

2020 | 104946 KM | auto | Diesel | 140 kw

Seller Disclosure



7266LLR

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	white
HP	140 kw
VIN	WBAVJ910809C98170
Technical Inspection	
DUA	No
Mise en circulation	17/12/2020
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique


Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO
 Emplacement -
Auction Centre Madrid


Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage : -
 Type de dommage : -
 Taille du dommage : -



Détail du dommage : -
 Type de dommage : -
 Taille du dommage : -