



CONDITION REPORT

2024 BMW iX1 xDrive30 (U11) iX1 xDrive30 (U11) 200HP

2024 | 4617 KM | auto | electric | 200 kw

Seller Disclosure



1128MVF

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	black
HP	200 kw
VIN	WBY61EF0605087271
Technical Inspection	
DUA	No
Mise en circulation	23/09/2024
Last Service Date	-

-  2^e CHAVE
-  CARNET D'ENTRETIEN
-  VAT
-  Vendus



Equipement

Notes publique

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
<a
href="http://soportemanheim.es/E/1128MVF.htm"
target="_blank">CLICK AQUÍ PARA VER
EL EQUIPAMIENTO
COMPLETO

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-