



CONDITION REPORT

2023 BMW iX1 xDrive30 (U11) iX1 xDrive30 (U11) 200HP

2023 | 15013 KM | auto | electric | 200 kw

Seller Disclosure



9603MKB

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	white
HP	200 kw
VIN	WBY61EF0105X49001
Technical Inspection	
DUA	No
Mise en circulation	30/08/2023
Last Service Date	-



2^e CHAVE




CARNET D'ENTRETIEN



VAT



Vendus



Equipement	Notes publique	Inspection
	POSIBILIDAD EXTRAVIO FT CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO	Emplacement - Auction Centre Madrid

Inspection
Emplacement - Auction Centre Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -



Détail du dommage : -
Type de dommage : -
Taille du dommage : -