



CONDITION REPORT

2023 Citroen C3 C3 BlueHDi 75KW (100CV) S&S Shine HP

2023 | 5943 KM | Manuelle | Diesel |

Seller Disclosure



9799MFX

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Negro techo blanco
HP	-
VIN	VF7SXYHTUNT649126
Technical Inspection	
DUA	No
Mise en circulation	31/03/2023
Last Service Date	-



2^a CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

Emplacement
 Auction Centre

-
 Madrid


Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-