



CONDITION REPORT

2021 Citroen JUMPER Citroen Jumper BlueHDi 103KW
(140CV) Furgón 35L3H2 HP

2021 | 104583 KM | Manuelle | Diesel |

Seller Disclosure



0041LSZ

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco Hielo (opaco)
HP	-
VIN	VF7YCBNFC12S94175
Technical Inspection	
DUA	No
Mise en circulation	24/09/2021
Last Service Date	-



2º CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Emplacement -
Auction Centre Madrid


Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-