



CONDITION REPORT

2020 BMW 116d (F40) 116d (F40) 85HP

2020 | 102369 KM | auto | Diesel | 85 kw

Seller Disclosure



5142LFX

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	grey
HP	85 kw
VIN	WBA7M710007F22712
Technical Inspection	
DUA	No
Mise en circulation	28/02/2020
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Emplacement Madrid-ES34
Auction Centre Madrid

Inspection

Emplacement Madrid-ES34
Auction Centre Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -



Détail du dommage : -
Type de dommage : -
Taille du dommage : -