



CONDITION REPORT

2024 BMW X1 xDrive20d (U11) X1 xDrive20d (U11) 110HP

2024 | 25177 KM | auto | Diesel | 110 kw

Seller Disclosure



6408MNZ

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Spacesilber
HP	110 kw
VIN	WBA41EG0405Y87619
Technical Inspection	
DUA	No
Mise en circulation	15/03/2024
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique


Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO
 Emplacement
 Valencia-ES28
 Auction Centre
 Madrid


Inspection

Emplacement
 Valencia-ES28
 Auction Centre
 Madrid


Damage Assesment




Détail du dommage : -
 Type de dommage : -
 Taille du dommage : -




Détail du dommage : -
 Type de dommage : -
 Taille du dommage : -



Détail du dommage : -
 Type de dommage : -
 Taille du dommage : -



Détail du dommage : -
 Type de dommage : -
 Taille du dommage : -



Détail du dommage : -
 Type de dommage : -
 Taille du dommage : -