



CONDITION REPORT

2019 Peugeot PARTNER Furgon Confort L1 1.6 BlueHDi
55KW (75) 75HP

2019 | 83369 KM | Manuelle | Diesel | 75 hp

Seller Disclosure



7523KWN

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco
HP	75 hp
VIN	VF37ABHW6JJ767530
Technical Inspection	
DUA	No
Mise en circulation	29/04/2019
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-