



CONDITION REPORT

2021 MERCEDES B-CLASS B 180 d 116HP

2021 | 134672 KM | auto | Diesel | 116 hp

Seller Disclosure



5984LVJ

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco digital (meta
HP	116 hp
VIN	W1K2470101J325749
Technical Inspection	
DUA	No
Mise en circulation	16/12/2021
Last Service Date	-



2^e CHAVE




CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-