



CONDITION REPORT

2022 BMW 118d (F40) 118d (F40) 110HP


2022 | 65514 KM | auto | Diesel | 110 kw

Seller Disclosure



1940LWB

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	white
HP	110 kw
VIN	WBA7M910607K36002
Technical Inspection	
DUA	No
Mise en circulation	26/01/2022
Last Service Date	-
2 ^e CHAVE	
CARNET D'ENTRETIEN	
VAT	
Vendus	



Equipement

Notes publique

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
<a
href="http://soportemanheim.es/E/1940LWB.htm"
target="_blank">CLICK AQUÍ PARA VER
EL EQUIPAMIENTO
COMPLETO

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-