



CONDITION REPORT

2019 Peugeot 308 5p Style BlueHDi 75KW (100CV) 100HP

2019 | 83767 KM | Manuelle | Diesel | 100 hp

Seller Disclosure



3379KXW

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Gris platinum
HP	100 hp
VIN	VF3LBYHYPKS236370
Technical Inspection	
DUA	No
Mise en circulation	11/06/2019
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-