



CONDITION REPORT

2021 Renault Nuevo COMFORT Nuevo MEGANE Zen Blue
dCi 85 kW (115CV) EDC -SS HP

2021 | 104429 KM | auto | Diesel |

Seller Disclosure



4448LNS

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	-
HP	-
VIN	VF1RFB00067153770
Technical Inspection	
DUA	No
Mise en circulation	14/04/2021
Last Service Date	-



2^e CHAVE




CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection


RSGALT-QPA\$RQ-RDIF29-PKFB0X

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -