



CONDITION REPORT

2021 LAND ROVER Range Rover Velar Land Rover Range
Rover Velar 2.0D I4 150kW (204CV) HP

2021 | 132807 KM | auto | Diesel |

Seller Disclosure



8138LNX

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Yulong White - metalizada
HP	-
VIN	SALYA2BNXMA312209
Technical Inspection	
DUA	No
Mise en circulation	26/04/2021
Last Service Date	-



2^e CHAVE




CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL


Inspection

Emplacement	Madrid
Auction Centre	Madrid

Inspection

Emplacement	Madrid
Auction Centre	Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-