



CONDITION REPORT

2021 Peugeot 3008 Peugeot 3008 1.5 BlueHDi 96kW (130CV)
S&S Allure t HP

2021 | 146789 KM | Manuelle | Diesel |

Seller Disclosure



0883LNG

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco Nacarado (3 capas)
HP	-
VIN	VF3MCYHZMMS080261
Technical Inspection	
DUA	No
Mise en circulation	22/03/2021
Last Service Date	-



2ª CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Emplacement	Madrid
Auction Centre	Madrid

Inspection

Emplacement	Madrid
Auction Centre	Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-