



CONDITION REPORT

2024 BMW 116d (F40) 116d (F40) 85HP

2024 | 10255 KM | Manuelle | Diesel | 85 kw

Seller Disclosure



0293MMV

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	-
HP	85 kw
VIN	WBA7M710407N51000
Technical Inspection	
DUA	No
Mise en circulation	18/01/2024
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Emplacement

Auction Centre

-

Madrid

Inspection

Emplacement

Auction Centre

-

Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -