



CONDITION REPORT

2021 BMW 116d (F40) 116d (F40) 85HP

2021 | 89125 KM | Manuelle | Diesel | 85 kw

Seller Disclosure



 **MANHEIM**
Auction Services
COX AUTOMOTIVE

5817LNS

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	grey
HP	85 kw
VIN	WBA7M710305T28233
Technical Inspection	
DUA	No
Mise en circulation	14/04/2021
Last Service Date	-



2^e CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
<a
href="http://soportemanheim.es/E/5817LNS.htm"
target="_blank">CLICK AQUÍ PARA VER
EL EQUIPAMIENTO
COMPLETO

Emplacement -
Auction Centre Madrid


Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -



Détail du dommage : -
Type de dommage : -
Taille du dommage : -