



CONDITION REPORT

2020 Peugeot PARTNER Pro Standard 600kg BlueHDi 73kW
furgón derivado de HP

2020 | 103464 KM | Manuelle | Diesel |

Seller Disclosure



3498LJV

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Banquise Blanco sólido - P0WP
HP	-
VIN	VR3EFYHYCLN529274
Technical Inspection	
DUA	No
Mise en circulation	11/09/2020
Last Service Date	-



2ª CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Emplacement	-
Auction Centre	Madrid

Inspection

Emplacement	-
Auction Centre	Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-