



CONDITION REPORT

2018 Volkswagen CADDY Profes Furgón 2.0 TDI 90kW BMT
4Motion furgón deri HP

2018 | 145309 KM | Manuelle | Diesel |

Seller Disclosure



5857KRR

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco Candy
HP	-
VIN	WV1ZZZ2KZX138376
Technical Inspection	
DUA	No
Mise en circulation	21/11/2018
Last Service Date	-



2º CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-