



CONDITION REPORT

2021 Peugeot 508 Peugeot 508 508 5P Allure BlueHDi 130
S&S EAT8 ber HP

2021 | 115240 KM | auto | Diesel |

Seller Disclosure



6065LNR

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Gris Platino (metalizado)
HP	-
VIN	VR3FBYHZTMY007153
Technical Inspection	
DUA	No
Mise en circulation	12/04/2021
Last Service Date	-



2^a CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Emplacement -
Auction Centre Madrid


Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-