



CONDITION REPORT

2019 Peugeot PARTNER (O) Furgon Confort L1 1.6 BlueHDi
55KW (75HP

2019 | 68064 KM | Manuelle | Diesel | 75 hp

Seller Disclosure

3714KTM

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Corporativo
HP	75 hp
VIN	VF37ABHW6JJ761838
Technical Inspection	
DUA	No
Mise en circulation	11/02/2019
Last Service Date	-

- ✗ 2^e CHAVE
- ✗ CARNET D'ENTRETIEN
- ✓ VAT
- ✗ Vendus



Equipement

Notes publique


Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Técnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement	-
Auction Centre	Madrid

Inspection

Emplacement	-
Auction Centre	Madrid



Détail du dommage : -

Type de dommage : -

Taille du dommage : -