



CONDITION REPORT

2022 DS DS 3 CROSSBACK PureTech 73 kW Manual
PERFORMANCE LINE 100HP

2022 | 91841 KM | Manuelle | | 100 hp


Seller Disclosure



4583LWP

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco banquise
HP	100 hp
VIN	VR1URHNEKMW108879
Technical Inspection	
DUA	No
Mise en circulation	28/02/2022
Last Service Date	-

- 2^e CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

IMPORTANT: VER PERITACIÓN
 (Informe Técnico) PARA COMPROBAR
 POSIBLES DAÑOS E INFORMACIÓN
 ADICIONAL


Inspection

Emplacement	-
Auction Centre	Madrid

Inspection

Emplacement	-
Auction Centre	Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -