



CONDITION REPORT

2019 Citroen C3 BlueHDi 73KW (100CV) S&S FEEL 99HP

2019 | 66133 KM | Manuelle | Diesel | 99 hp


Seller Disclosure



7229KWV

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco
HP	99 hp
VIN	VF7SXYHYPKT586918
Technical Inspection	
DUA	No
Mise en circulation	07/05/2019
Last Service Date	-

- 2^e CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement	-
Auction Centre	Madrid

Inspection

Emplacement	-
Auction Centre	Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -