



CONDITION REPORT

2022 Citroen C3 BlueHDi 75KW (100CV) S&S Live Pack
102HP


2022 | 64936 KM | Manuelle | Diesel | 102 hp

Seller Disclosure



9980LXJ

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco banquise
HP	102 hp
VIN	VF7SXYHTUNT539335
Technical Inspection	
DUA	No
Mise en circulation	20/04/2022
Last Service Date	-
2 ^e CHAVE	
CARNET D'ENTRETIEN	
VAT	
Vendus	



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Emplacement	-
Auction Centre	Madrid

Inspection

Emplacement	-
Auction Centre	Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-