



CONDITION REPORT

2020 BMW X1 xDrive25e (F48) X1 xDrive25e (F48) 162HP

2020 | 116732 KM | auto | Petrol | 162 kw

Seller Disclosure



4264LKT

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	black
HP	162 kw
VIN	WBA71AB0105S35148

Technical Inspection

DUA	No
Registration Date	30-10-2020
Last Service Date	-

-  2^e CHAVE
-  ONDERHOUDSBOEKJE
-  VAT
-  Sold as Seen



Equipment	Public Notes	Inspection
	POSIBILIDAD EXTRAVIO FT CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO	Location- Auction CentreMadrid


Inspection

Location-
Auction CentreMadrid


Damage Assesment




Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-