



CONDITION REPORT

2024 BMW M235i xDrive Gran Coupé (F44) M235i xDrive Gran Coupé (F44) 225HP

2024 | 15730 KM | auto | Petrol | 225 kw

Seller Disclosure



4526MRG

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	black
HP	225 kw
VIN	WBA11AL0807P42251
Technical Inspection	
DUA	No
Registration Date	08-05-2024
Last Service Date	-



2^o CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIDIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid


Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -