



# CONDITION REPORT

2019 BMW X1 X1 1.5 SDRIVE16D 116HP

2019 | 99700 KM | Manual | DIESELMOTOR | 116 hp

Seller Disclosure



**8881LDC**

Engine Size	1496 cm3
Seats	-
Number of Doors	5
Body Style	-
Body Colour	BLANCO
HP	116 hp
VIN	WBA31AC0105P42628
Technical Inspection	
DUA	No
Registration Date	12-12-2019
Last Service Date	-

- ✘ 2ª CHAVE
- ✘ ONDERHOUDSBOEKJE
- ✔ VAT
- ✘ Sold as Seen



### Equipment

### Public Notes

### Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> **Location** Madrid  
**Auction Centre** Madrid **CALCULA TU TRANSPORTE**

### Inspection

**Location** Madrid  
**Auction Centre** Madrid

## Damage Assessment

---



Damage Detail : -

Damage Type : -

Damage Size : -