



CONDITION REPORT

2019 Mini Cooper S E All4 (F60) Cooper S E All4 (F60) 165HP

2019 | 140510 KM | auto | Petrol | 165 kw

Seller Disclosure



 **MANHEIM**
Auction Services
COX AUTOMOTIVE

4511LCW

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Melting Silver
HP	165 kw
VIN	WMWYU710403L61113
Technical Inspection	
DUA	No
Registration Date	28-11-2019
Last Service Date	-



2^e CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen




Equipment	Public Notes	Inspection	
	POSIBILIDAD EXTRAVIO FT EQUIPAMIENTO: ACC.CONF ; ASI.DEP ; ASI.DEP ; ASIST.APARC ; AUT ; CAM.TRAS* ; CC ; LED ; NAV* ; PDC ; Perform.Ctrl	Location	Madrid
		Auction Centre	Madrid


Inspection

Location	Madrid
Auction Centre	Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -