



# CONDITION REPORT

2019 OPEL COMBO COMBO 1.6 TD 74KW EXPRESS 650KG  
S/S SWB 100HP

2019 | 40937 KM | Manual | DIESELMOTOR | 100 hp

Seller Disclosure



## 2096LDB

Engine Size	1560 cm3
Seats	-
Number of Doors	3
Body Style	-
Body Colour	BLANCO
HP	100 hp
VIN	W0VEFYHYCLN500716
Technical Inspection	
DUA	No
Registration Date	05-12-2019
Last Service Date	-

- ✘ 2ª CHAVE
- ✘ ONDERHOUDSBOEKJE
- ✔ VAT
- ✘ Sold as Seen



### Equipment

### Public Notes

### Inspection

[CALCULA TU TRANSPORTE](https://www.manheimtransportatucoche.es/es/transportas/manheim)


Location -  
Auction Centre Madrid

### Inspection


Location -  
Auction Centre Madrid

## Damage Assessment


---



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -