



CONDITION REPORT

2020 BMW SERIE 1 SERIE 1 2.0 118D 150HP
2020 | 102013 KM | Manual | DIESELMOTOR | 150 hp
Seller Disclosure



7370LLW

Engine Size	1995 cm3
Seats	-
Number of Doors	5
Body Style	-
Body Colour	NEGRO GRIS METALIZ
HP	150 hp
VIN	WBA7M910X07H44623
Technical Inspection	
DUA	No
Registration Date	23-12-2020
Last Service Date	-

- ☒ 2ª CHAVE
- ☒ ONDERHOUDSBOEKJE
- ☒ VAT
- ☒ Sold as Seen



Equipment

Public Notes

Inspection


<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assessment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -