



CONDITION REPORT

2021 BMW 116d (F40) 116d (F40) 85HP

2021 | 123601 KM | auto | DIESELMOTOR | 85 kw

Seller Disclosure



2685LNG

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	85 kw
VIN	WBA7M710107H94217
Technical Inspection	
DUA	No
Registration Date	23-03-2021
Last Service Date	-



2ª CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
EQUIPAMIENTO:
;
ACC.CONF ; ASI.CAL ; CC ; LED ;
PAQ.Business ; PDC ; STEPTRONIC

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -