



CONDITION REPORT

2021 BMW BMW i3 (I01) BMW i3 (I01) 125HP

2021 | 78027 KM | auto | electric | 125 kw

Seller Disclosure



 **MANHEIM**
Auction Services
COX AUTOMOTIVE

0914LMN

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Melbourne Rot con detalles Frozen Grey metalizado
HP	125 kw
VIN	WBY8P210X07G13518
Technical Inspection	
DUA	No
Registration Date	09-02-2021
Last Service Date	-

-  2º CHAVE
-  ONDERHOUDSBOEKJE
-  VAT
-  Sold as Seen



Equipment

Public Notes

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
<a
href="http://soportemanheim.es/E/0914LMN.htm"
target="_blank">CLICK AQUÍ PARA VER
EL EQUIPAMIENTO
COMPLETO

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -