



CONDITION REPORT

2020 BMW M850i xDrive Gran Coupé (G16) M850i xDrive
Gran Coupé (G16) 390HP

2020 | 116598 KM | auto | Petrol | 390 kw

Seller Disclosure



2561LHM

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	390 kw
VIN	WBAGV81060CE71209
Technical Inspection	
DUA	No
Registration Date	10-07-2020
Last Service Date	-



2^a CHAVE



ONDERHOUDSBOEKJE



VAT








Sold as Seen



Equipment	Public Notes	Inspection
	POSIBILIDAD EXTRAVIO FT CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid

Damage Assesment

 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -
 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	