



CONDITION REPORT

2019 BMW X1 X1 SDRIVE18DA BUSINESS(CAM) 150HP

2019 | 148215 KM | Manual | DIESELMOTOR | 150 hp

Seller Disclosure



3898KTN

Engine Size	1995 cm3
Seats	-
Number of Doors	5
Body Style	-
Body Colour	BLANCO
HP	150 hp
VIN	WBAJH51090EK97326
Technical Inspection	
DUA	No
Registration Date	13-02-2019
Last Service Date	-

- 2ª CHAVE
- ONDERHOUDSBOEKJE
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection


[MANHEIM](https://www.manheimtransportatucoche.es/es/transportes/manheim) [CALCULA TU TRANSPORTE](#)

Location Madrid
Auction Centre Madrid

Inspection

Location Madrid
Auction Centre Madrid

Damage Assessment



Damage Detail : -

Damage Type : -

Damage Size : -