



CONDITION REPORT

2020 HYUNDAI TUCSON TUCSON (O)1.6 CRDI 85KW 48V SLE 2WD 116HP

2020 | 149742 KM | Manual | DIESELMOTOR | 116 hp

Seller Disclosure



9313LGK

Engine Size	1598 cm3
Seats	-
Number of Doors	5
Body Style	-
Body Colour	MICRON GREY
HP	116 hp
VIN	TMAJ3817ALJ980915
Technical Inspection	
DUA	No
Registration Date	22-05-2020
Last Service Date	-

- 2ª CHAVE
- ONDERHOUDSBOEKJE
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection


<https://www.manheimtransportatucoche.es/es/transportes/manheim> > CALCULA TU TRANSPORTE

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assessment



Damage Detail : -

Damage Type : -

Damage Size : -